


Vector Training Center


Assessment 1

Learning Outcome	Maximum Marks	Marks Obtained
5	5	
Instructions	Answer all 5 Questions Choose and write the correct Letter in the Box	

Q. Identify following piping symbols



1.



2.



4.



3.



5.

- A. Lap joint Flange
- B. Flange Connected Gate Valve
- C. Pressure Indicating Controller
- D. Temperature Indicator
- E. Flanged Butterfly Valve
- F. Flanged Pressure relief Valve
- G. 90 Elbow Flanged

Vector Training Center

Assessment 1

Learning Outcome	Maximum Marks	Marks Obtained
6	5	
Instructions	Answer all 5 Questions Choose and write the correct Letter in the Box	



1.



2.



3.



4.

- A. Flanged Joint
- B. Pressure Joint
- C. Butt Fusion Welding
- D. Tight Joint
- E. Push-on Socket-Spigot Joint
- F. Solvent Cementing Joint
- G. Loctite Joint
- H. Threaded Joint
- I. Electro fusion welding
- J. Electric Welding Joint



5.